

# LS GACZ12S plain bearings

How do I place an EMERGENCY order 5 in d for a LS GACZ12S plain bearings that I want to pick Cast Bronze material: up at a our store?

|                              |   |
|------------------------------|---|
| material:                    | Cast Bronze                             |
| maximum p value:             | 4000 psi                                |
| d                            | 5 in                                    |
| maximum pv value:            | 75000                                   |
| D                            | 9 in                                    |
| maximum v value:             | 750 fp/min                              |
| overall length:              | 13 in                                   |
| groove/plug type:            | None                                    |
| material specification:      | SAE 660 (C932)                          |
| standards met:               | 83-7-7-3, ASTM B505, CDA 932, ASTM B271 |
| operating temperature range: | -450 to 500 °F °F                       |