

# RHP LRJ4.1/2 cylindrical roller bearings

Our highly-skilled and factory-trained service N/A Minimum Buy Quantity experts have the resources to help you with all your RHP LRJ4.1/2 cylindrical roller bearings needs – including routine maintenance, 0.0 Inventory major repairs, warranty service, and equipment inspections.

|                      |        |
|----------------------|--------|
| Inventory            | 0.0    |
| Manufacturer Name    | TIMKEN |
| Minimum Buy Quantity | N/A    |
| Weight               | 10.886 |
| Product Group        | M06288 |